

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 901 JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 28 N	Longitude: 122 36 10 W
Township: 02S	Range: 02E	Section: 31	Block: 66
Lot: 4x		Map #: 22E31AA	Tax Lot #: 9400
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Hip / Composition shingle		Window Type/Material: 1/1 wood double-hung; 8-pane fixed	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Front windows, c.1950; addition to north with aluminum slider; CMU foundation portions			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Excellent	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This c.1900 vernacular house is square in plan with a hip roof at the center section of the structure, a front facing gable at the front, entrance section and a low-hip roof at the rear structure. Wood shingles clad the gabled end pediment, which has eave returns at the main elevation. In some locations, evidence remains of the original board formed concrete. The windows are 1/1 wood double-hung on all elevations with a 8-pane horizontal, c. 1950s window at the front elevation. The exterior is clad in wood shingle siding. Alterations include a modern, non-historic metal entrance door with screen and portions of the foundation have been reconstructed with concrete block. An early two car garage exists to the east of the structure.			
Statement of Significance:			

Researcher/Organization: Christy Fockler / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 901 JOHN ADAMS ST	Local Designation #	SHPO #