

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 605 JQ ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 14 N	Longitude: 122 36 05 W
Township: 02S	Range: 02E	Section: 31 Block: 139 Lot: 3x	Map #: 22E31AD Tax Lot #: 8700
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - duplex	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Complex	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl with snap grids	
Exterior Surface Materials Primary: Channel drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Many additions to the back and north side; front porch; window replacement			
Number and Type of Associated Resources: None			
Integrity: Poor	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
The 1-1/2 story vernacular duplex has a gable roof covered in composition shingles. It has a complex plan and a concrete foundation with a vertical plywood siding skirt. The house is clad in channel drop siding and features a wide rakeboard and frieze, as well as corner boards. The windows have been replaced with 1/1 vinyl windows with snap grids. They have simple wood trim moldings. The front porch on the main unit is not compatible with the structure and is an addition. It features turned columns, engaged columns, and fancy brackets. Its shed roof runs the length of the front elevation. The second living unit was attached post c. 1950. Additions and alterations have been made to the back of the house. Wing projections have been made to the north side that may be an attachment of a remnant structure. The house sits right at the sidewalk and does not feature any yard or landscaping.			
Statement of Significance:			

Researcher/Organization: Jessica Engeman / HPNW		Date Recorded: 4/6/2002	
Survey Form Page 1	Address: 605 JQ ADAMS ST	Local Designation #	SHPO #