

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 712 JQ ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 16 N	Longitude: 122 36 01 W
Township: 02S	Range: 02E	Section: 31 Block: 157 Lot: 6x	Map #: 22E31AD Tax Lot #: 6100
Date of Construction: c. 1915	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Small shed with ramp attached to south side of house that provides basement access; alterations to front porch c. 1950; siding			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This bungalow style house has a steep gable roof with a large shed wall dormer extending out of the north side and is covered in composition shingles. Its plan is square and it sits on a poured concrete foundation. The house is clad in asbestos ceramic shingles and features wide bargeboards, decorative brackets, notched rafter tails, and a roman brick half-wall. The windows are primarily 1/1 wood with simple wide wood trim. The house still features its original front door. The owner recently removed the asbestos shingles on the south side to reveal the original double drop siding in good condition. At the rear of the house is a patio covered by a shed roof. The original back porch was demolished in favor of a 1950s motif.			
Statement of Significance:			
Researcher/Organization: Jessica Engeman / HPNW			Date Recorded: 4/6/2002
Survey Form Page 1	Address: 712 JQ ADAMS ST	Local Designation #	SHPO #