

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 723 JQ ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 18 N	Longitude: 122 36 01 W
Township: 02S	Range: 02E	Section: 31 Block: 140 Lot: 1	Map #: 22E31AD Tax Lot #: 5500
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 6/1 wood with fixed storms	
Exterior Surface Materials Primary: Stucco		Secondary: Wood shingle	Decorative:
Exterior Alterations or Additions/Approximate Date: Stucco; some window replacements			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 bungalow house has a cross gable roof covered in composition shingles. It has a square plan and sits on a poured concrete foundation. The primary exterior surfacing is non-original stucco, though the gables do feature imbrication with octagonal wood shingles. The windows are primarily 6/1 wood with fixed storms. Most of the windows are grouped and surrounded by a wide trim. The porch features a rounded entablature, bargeboards, decorative brackets, and an enclosed railing clad in lap siding. There is a shed roof over the north side entry and a chimney on the south side. There is also a garden lean-to in the back yard, as well as a large pine tree.			
Statement of Significance:			

Researcher/Organization: Jessica Engeman / HPNW		Date Recorded: 4/6/2002	
Survey Form Page 1	Address: 723 JQ ADAMS ST	Local Designation #	SHPO #