

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 117 MADISON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 05 N	Longitude: 122 36 23 W
Township: 02S	Range: 02E	Section: 31 Block: 13	Lot: 8x, 9x Map #: 22E31DB Tax Lot #: 1700
Date of Construction: 1939	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Jerkinhead / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Picture windows on south; column bases are plywood; eave brackets have been removed; addition to rear.			
Number and Type of Associated Resources: 1990s shop to north (1)			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story bungalow is rectangular in plan and sits on a concrete foundation. The jerkinhead roof is covered in composition shingles and is pierced by a chimney. The house is covered with lap siding. Windows are primarily 1/1 wood double-hung. The multi-light front door is original. The jerkinhead roof entry porch is supported by battered columns and has knee walls. An exterior brick chimney highlights its north wall. There is a detached 1990s shop to the north.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 117 MADISON ST	Local Designation #	SHPO #