

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 407 MONROE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 10 N	Longitude: 122 36 14 W
Township: 02S	Range: 02E	Section: 31 Block: 132 Lot: 3x	Map #: 22E31DA Tax Lot #: 3700
Date of Construction: c. 1930	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Traditional		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Fixed and double-hung vinyl with grid	
Exterior Surface Materials Primary: Vinyl		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Porch enclosed at entrance, date unknown.			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Excellent	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This c.1930 minimal tract house has a square plan with a side facing gable roof. A center gable roof covers an enclosed entrance porch. Boxed in soffits with diminutive eave returns are present below the eaves. The majority of windows are non-historic fixed vinyl windows with a grid. Some windows on the rear elevation are 8-pane or 7-pane windows with diamond shaped panes. An exposed brick chimney is present on the south elevation. Alterations include a non-historic wood porch with a deck, balustrade and railing flanking the main entrance.			
Statement of Significance:			
Researcher/Organization: Christy Fockler / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 407 MONROE ST	Local Designation #	SHPO #