

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>410 MONROE ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 12 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>137</b> Lot: <b>6x</b>	Map #: <b>22E31DA</b> Tax Lot #: <b>3400</b>
Date of Construction: <b>1946</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>WWII-era Cottage</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>2/2 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Drop</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Vinyl windows</b>			
Number and Type of Associated Resources: <b>Garage to north (1)</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
<p>This uncomplicated c.1946 cottage has a rectangular plan with a front facing gable roof. A small pedimented gable roof overhangs a small entrance porch supported by large triangular brackets. The typical window type is a 2/2 wood double-hung window. There are windows located at the corners of the structure, which are indicative of the "40's cottage" style. Two non-historic fixed vinyl windows with a grid are present on the front elevation. The exterior is clad with a multi-width wood drop siding throughout.</p> <p>A detached garage exists to the south of the main structure clad with multi-width wood drop siding and a gable roof. The original hinged doors are present on the garage.</p>			
Statement of Significance:			

Researcher/Organization: <b>Christy Fockler / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>410 MONROE ST</b>	Local Designation #	SHPO #