

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>914-918 MONROE ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 23 N</b>	Longitude: <b>122 35 58 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b>	Block: <b>142</b> Lot: <b>7x</b>
Date of Construction: <b>1946</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - duplex</b>	Associated Archaeological Site: <b>Unknown</b>	

Architectural Classification(s): <b>Minimal Tract</b>	Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>	Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Hip / Composition shingle</b>	Window Type/Material: <b>2/2 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Metal</b>	Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Modern front doors and handrails</b>		
Number and Type of Associated Resources: <b>None</b>		

Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			

Description of Physical and Landscape Features:

This c.1946 residence is a multi-unit complex of three apartments. There are two structures, one facing the street and the other detached behind the main structure. The main structure is a duplex and is square in plan with a hipped roof. The smaller single unit behind has a rectangular plan with a gabled roof. The windows are typically a 2/2 wood double-hung with 1/1 wood double-hung in some locations. A fixed 6-pane picture window is present on the front elevation of the duplex. Alterations include the addition of concrete steps and a metal handrail leading up to the duplex structure from the street. A brick half wall exists at the front elevation

Statement of Significance:

---

Researcher/Organization: <b>Christy Fockler / HPNW</b>	Date Recorded: <b>4/12/2002</b>
<b>Survey Form Page 1</b>	Address: <b>914-918 MONROE ST</b>
Local Designation #	SHPO #