

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1114 MONROE ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 28 N</b>	Longitude: <b>122 35 54 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b> Block: <b>144</b> Lot: <b>7x</b>	Map #: <b>22E32BB</b> Tax Lot #: <b>8100</b>
Date of Construction: <b>c. 1950</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Minimal Tract</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Hip / Composition shingle</b>		Window Type/Material: <b>Vinyl with grid</b>	
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Windows are vinyl grid</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b> Condition: <b>Fair</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input checked="" type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This basic c.1950 minimal tract house is square in plan with a hipped roof and no eaves. A small shed roof covers the main entrance porch and is attached directly to the main structure. The exterior is clad in wood lap siding and is in disrepair. The windows are non-historic vinyl with an inserted grid. A fixed vinyl window and double-hung vinyl windows with grid are present at the front elevation. A detached shed with a gambrel roof is present at the rear of the structure. Alterations include the vinyl window replacements and porch cover.			
Statement of Significance:			
Researcher/Organization: <b>Christy Fockler / HPNW</b>			Date Recorded: <b>4/12/2002</b>
<b>Survey Form Page 1</b>	Address: <b>1114 MONROE ST</b>	Local Designation #	SHPO #