

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1301 MONROE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 33 N	Longitude: 122 35 51 W
Township: 02S	Range: 02E	Section: 32 Block: 123 Lot: 4	Map #: 22E32BB Tax Lot #: 3900
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow / Colonial		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Jerkinhead / Composition shingle		Window Type/Material: 15-pane casement	
Exterior Surface Materials Primary: Vinyl		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Enclosed porch on north elevation			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Excellent	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This small c.1925 Colonial bungalow residence has a rectangular shaped plan with a jerkinhead roof. Large triangular brackets support a small gabled entry porch hood. The front entrance door is a non-historic wood paneled door. The exterior is clad in modern vinyl channel siding. A 15-pane casement window is present at the front elevation and 1/1 wood double-hung windows are typical at all other elevations. Alterations include an enclosed porch on the north elevation of the structure with non-historic fixed picture windows and a rectangular fixed transom above and a non-historic wood deck addition at the rear elevation. A detached garage with a flat roof and horizontal wood siding exists to the north of the structure.			
Statement of Significance:			

Researcher/Organization: Christy Fockler / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 1301 MONROE ST	Local Designation #	SHPO #