

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 118 PROMENADE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 12 N	Longitude: 122 36 41 W
Township: 02S	Range: 02E	Section: 31 Block: 73 Lot: 2x	Map #: 22E31CA Tax Lot #: 200
Date of Construction: c. 1945	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Colonial		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 8/1 wood double-hung	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed roof over entry added.			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This house sits under a side gable roof with two gabled dormers on the west façade. Centered on this façade is the main entry to the house, covered by a small shed roof that is an addition to the house. The gables feature shallow enclosed eaves and decorative barge moldings. The house is entirely clad with lap siding with decorative corner moldings. The windows are predominantly 8/1 double-hung wood sash, but two large fixed panes with seven-pane transoms flank the central west entry. The windows typically feature narrow trim moldings.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 118 PROMENADE ST	Local Designation #	SHPO #