

### OREGON CITY HISTORIC RESOURCE SURVEY FORM

|   |  |  |  |
|---|--|--|--|
| Street Address: <b>714 SPRING ST</b>  |  | City: <b>OREGON CITY</b>                                       |  |
| USGS Quad Name: <b>Oregon City</b>  |  | GPS Latitude: <b>45 21 05 N</b>                                | Longitude: <b>122 36 30 W</b>  |
| Township: <b>02S</b>  | Range: <b>02E</b>  | Section: <b>31</b>   | Block: <b>NA</b> Lot: <b>NA</b> Map #: <b>22E31DB</b> Tax Lot #: <b>7700</b>         |
| Date of Construction:<br><b>c. 1942</b>   | Historic Name:   | Historic Use or Function:<br><b>Domestic - single dwelling</b> |  |
| Grouping or Cluster Name:<br><b>NA</b>  | *Current Name or Use:<br><b>Domestic - single dwelling</b> | Associated Archaeological Site:<br><b>Unknown</b>              |  |
| Architectural Classification(s): <b>Minimal Tract</b>   |  | Plan Type/Shape: <b>Complex</b>                                | Number of Stories: <b>1.0</b>  |
| Foundation Material: <b>Concrete</b>  |  | Structural Framing: <b>Unknown</b>                             | Moved? <b>No</b>   |
| Roof Type/Material: <b>Gable / Composition shingle</b>  |  | Window Type/Material: <b>2/2 wood double-hung</b>              |  |
| Exterior Surface Materials Primary: <b>Lap</b>  |  | Secondary:   | Decorative:  |
| Exterior Alterations or Additions/Approximate Date: <b>Storm windows added; garage door replaced.</b>   |  |  |  |
| Number and Type of Associated Resources: <b>Garage to SW (1)</b>  |  |  |  |
| Integrity: <b>Good</b> Condition: <b>Good</b>   |  | Local Ranking:   | National Register Listed? <b>No</b>  |
| Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district<br>Not Eligible: <input type="checkbox"/> Intact but lacks distinction<br><input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district<br><input type="checkbox"/> Reversible/Ineligible as it lacks distinction<br><input type="checkbox"/> Irretrievable loss of integrity<br><input type="checkbox"/> Not 50 years old  |  |  |  |
| Description of Physical and Landscape Features:   |  |  |  |
| <p>This modest house sits under a side gable roof, with a small gable projecting out from the north side of the house over the enclosed entryway. A rectangular bay projects out to the west from the south end of the west façade, covered by its own gable. The gables typically feature shallow enclosed eaves, and the entry gable has wide barge boards. The house is entirely clad with lap siding, and features 2/2 double-hung wood sash windows with horizontally oriented panes, typical of the era. The windows are typically trimmed by narrow trim molding without sills.</p> <p>A garage is located to the southwest of the house, and has a single overhead door. The garage is clad with the same material as the house, and its front gable roof is similar in character to the gables on the house.</p> |  |  |  |
| Statement of Significance:  |  |  |  |
|   |  |  |  |

|   |                               |                                 |        |
|---|-------------------------------|---------------------------------|--------|
| Researcher/Organization: <b>Alex McMurry / HPNW</b> |                               | Date Recorded: <b>3/26/2002</b> |        |
| <b>Survey Form Page 1</b>                           | Address: <b>714 SPRING ST</b> | Local Designation #             | SHPO # |