

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1215 VAN BUREN ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 27 N	Longitude: 122 35 42 W
Township: 02S	Range: 02E	Section: 32 Block: 170 Lot: 2x	Map #: 22E32BB Tax Lot #: 6600
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Round-edge drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Rear porch enclosed and added on to			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Excellent		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
The bungalow exhibits a wide overhang of its gable roof, with brackets supporting a pointed barge board. The entry porch is made up of a smaller gable with similar detailing. Round edge double drop siding covers the structure down to the water table. Below the water table, tongue and groove boards run horizontal. Significant alterations include enclosure of a rear porch, and addition on the rear. Windows are a 1/1 wood double-hung with lamb's tongue detailing. The front door appears to be original.			
Statement of Significance:			
Researcher/Organization: Joe Snider / HPNW			Date Recorded: 5/22/2002
Survey Form Page 1	Address: 1215 VAN BUREN ST	Local Designation #	SHPO #