

OREGON CITY HISTORIC RESOURCE SURVEY FORM

| | | | |
|---|--|--|--|
| Street Address: 724 VAN BUREN ST | | City: OREGON CITY | |
| USGS Quad Name: Oregon City | | GPS Latitude: 45 21 14 N | Longitude: 122 35 54 W |
| Township: 02S | Range: 02E | Section: 32 Block: 35 Lot: 8 | Map #: 22E32BC Tax Lot #: 9900 |
| Date of Construction: c. 1915 | Historic Name: | Historic Use or Function: Domestic - single dwelling | |
| Grouping or Cluster Name: NA | *Current Name or Use: Domestic - single dwelling | Associated Archaeological Site: Unknown | |
| Architectural Classification(s): Bungalow | | Plan Type/Shape: Rectangle | Number of Stories: 1.5 |
| Foundation Material: Concrete | | Structural Framing: Unknown | Moved? No |
| Roof Type/Material: Gable / Composition shingle | | Window Type/Material: 1/1 wood double-hung | |
| Exterior Surface Materials Primary: Vinyl | | Secondary: | Decorative: |
| Exterior Alterations or Additions/Approximate Date: Vinyl siding added; vertical siding as skirt over foundation; shed roof lean-to porch on back | | | |
| Number and Type of Associated Resources: None | | | |
| Integrity: Good | Condition: Excellent | Local Ranking: | National Register Listed? No |
| Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old | |  | |
| Description of Physical and Landscape Features: | | | |
| This bungalow exhibits craftsman detailing in its brackets, rafter tails, and windows. The windows all appear to be original wood and are currently covered with metal storm windows. Sitting on a hill up off the street, a two level stair leads up to the front porch, though these railings are recent wood additions. Most notably, the house is now covered with vinyl siding, including vertical groove plywood as a skirt covering the foundation. A small lean-to porch on the back (west) elevation appears to be a later addition. The house sits under a large gable with a smaller gable to the north that serves as an entry porch. A shed dormer protrudes on the north side of the main dormer. | | | |
| Statement of Significance: | | | |
| | | | |
| Researcher/Organization: Joe Snider / HPNW | | | Date Recorded: 5/16/2002 |
| Survey Form Page 1 | Address: 724 VAN BUREN ST | Local Designation # | SHPO # |