

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 922 VAN BUREN ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 19 N	Longitude: 122 35 48 W
Township: 02S	Range: 02E	Section: 32	Block: NA Lot: NA Map #: 22E32BC Tax Lot #: 3500
Date of Construction: c. 1930	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 4/1 wood double-hung	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding covered with wood shingles; dormer added on rear side of gable			
Number and Type of Associated Resources: Garage (1)			
Integrity: Good Condition: Excellent		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This bungalow sits on a corner lot on grade with the sidewalk. An associated garage sits facing 10th street. The gable roof has wide overhanging eaves with some exposed fascia board detailing and brackets. The wood windows consist of 4 panes above one larger operable pane. A gabled entry with brackets faces the street. Both house and garage have since had their small wood shingle siding covered with wider and larger wood shingles. This is evident upon close examination, as one can see the older shingles beneath the newer ones.			
Statement of Significance:			

Researcher/Organization: Joe Snider / HPNW		Date Recorded: 5/22/2002	
Survey Form Page 1	Address: 922 VAN BUREN ST	Local Designation #	SHPO #