

OREGON CITY HISTORIC RESOURCE SURVEY FORM

| | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|----------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Street Address: 203 WASHINGTON ST | | City: OREGON CITY | |
| USGS Quad Name: Oregon City | | GPS Latitude: 45 21 10 N | Longitude: 122 36 32 W |
| Township: 02S | Range: 02E | Section: 31 Block: 58 Lot: 4x | Map #: 22E31AC Tax Lot #: 14800 |
| Date of Construction: c. 1918 | Historic Name: | Historic Use or Function: Domestic - single dwelling | |
| Grouping or Cluster Name: NA | *Current Name or Use: Domestic - single dwelling | Associated Archaeological Site: Unknown | |
| Architectural Classification(s): Bungalow | | Plan Type/Shape: Rectangle | Number of Stories: 1.5 |
| Foundation Material: Concrete | | Structural Framing: Unknown | Moved? No |
| Roof Type/Material: Gable / Composition shingle | | Window Type/Material: 1/1 vinyl | |
| Exterior Surface Materials Primary: Round-edge drop | | Secondary: | Decorative: |
| Exterior Alterations or Additions/Approximate Date: Full window replacement | | | |
| Number and Type of Associated Resources: Garage to rear (1) | | | |
| Integrity: Good Condition: Good | | Local Ranking: | National Register Listed? No |
| Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old | | |  |
| Description of Physical and Landscape Features: | | | |
| <p>This 1-1/2 story bungalow has a rectangular plan with a full width hipped front porch. It sits on a concrete foundation and appears to be clad in round edge drop siding above the porch roof and simple beveled siding below it. There are also corner boards and a wide water table. The front gabled roof is covered with composition shingling. There is a large bargeboard with brackets. The windows have been fully replaced by 1/1 vinyl. The front porch has a hip roof supported by boxed columns, with simple pilasters where the porch meets the front wall. The porch railing is enclosed and clad in round edge drop siding, with front drainage openings. The concrete stairs have wrought iron railings.</p> <p>There is a detached garage to the rear of the house. It is gabled and has the same siding and trim detailing as the main house. The windows have also been changed to vinyl and the garage door is new.</p> | | | |
| Statement of Significance: | | | |
| | | | |
| Researcher/Organization: Carin Petersen / HPNW | | | Date Recorded: 5/11/2002 |
| Survey Form Page 1 | Address: 203 WASHINGTON ST | Local Designation # | SHPO # |