

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>607 WASHINGTON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 22 N</b>	Longitude: <b>122 36 21 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>54</b>
Lot: <b>3x</b>		Map #: <b>22E31AC</b>	Tax Lot #: <b>500</b>
Date of Construction: <b>1947</b>	Historic Name:	Historic Use or Function: <b>Commerce - store</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Commerce - retail trade</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Modern Commercial</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Flat / Built-up</b>		Window Type/Material: <b>Metal casement; large fixed</b>	
Exterior Surface Materials Primary: <b>Concrete block</b> Secondary: <b>Vertical groove plywo</b> Decorative:			
Exterior Alterations or Additions/Approximate Date: <b>Vertical groove plywood frieze</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually    or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input checked="" type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This single story commercial store has a rectangular plan. It sits on a concrete foundation and is constructed of concrete block. The flat roof slopes to the west and has exposed tapered rafter tails. The ends of the roof beams also protrude from the north and south facades. The windows are primarily steel casement with security bars. The front facade is clad on the upper half with vertical groove plywood and has a string of six large store front windows.			
Statement of Significance:			

Researcher/Organization: <b>Carin Petersen / HPNW</b>		Date Recorded: <b>5/11/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>607 WASHINGTON ST</b>	Local Designation #	SHPO #