

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 408 S 1ST ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 06 N	Longitude: 122 36 43 W
Township: 02S	Range: 02E	Section: 31	Block: 80
Lot: 8x		Map #: 22E31CA	Tax Lot #: 6000
Date of Construction: c. 1930	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Round-edge drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Screened in porch; new front door; huge dormer addition to east side; deck on east side, 1990.			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story bungalow is rectangular in plan. The gable roof is covered in composition shingles and has decorative eave brackets. The house is covered with round-edge drop siding ground by a water table, cap, and vertical wood foundation skirting. Windows are primarily 1/1 wood double-hung. The gable roof entry porch has battered columns and knee wall. There is a 3-sided bay on the west side. There is a two story addition on the rear (south) façade.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/6/2002	
Survey Form Page 1	Address: 408 S 1ST ST	Local Designation #	SHPO #