

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 412 S 1ST ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 06 N	Longitude: 122 36 42 W
Township: 02S	Range: 02E	Section: 31	Block: 80
Lot: 1x		Map #: 22E31CA	Tax Lot #: 6100
Date of Construction: 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl; fixed wood with leaded glass	
Exterior Surface Materials Primary: Round-edge drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: New front door; front steps rebuilt			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Excellent	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This front-facing bungalow has a gable roof covered in composition shingles. It sits on an undetermined foundation skirted by vertical groove plywood. The house is clad in round-edge drop siding. A full-width porch dominates the front elevation. The porch has a solid rail and non-descript posts. A new stair and rail access the porch. The front door has been replaced. Windows are primarily 1/1 wood double-hung with storms. Brackets decorate the eave.			
Statement of Significance:			
Researcher/Organization: David Pinyerd / HPNW			Date Recorded: 4/16/2002
Survey Form Page 1	Address: 412 S 1ST ST	Local Designation #	SHPO #