

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>414 S 2ND ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 03 N</b>	Longitude: <b>122 36 44 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>79</b> Lot: <b>1</b>	Map #: <b>22E31CA</b> Tax Lot #: <b>7300</b>
Date of Construction: <b>c. 1913</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Complex</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete block</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Multi-pane casement</b>	
Exterior Surface Materials Primary: <b>Wood shingle</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Flat roof I-shaped addition; gable roof garage at rear of addition; new wood shingles; new front door</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story vernacular house is complex in plan, due to subsequent additions, and sits on a concrete foundation. The gable roof, flared on one side, is covered in composition shingles. The house is covered with wood shingles. Windows are primarily multi-pane casement. A flat roof I-shaped addition connects the house to the gable roof single-car garage.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>5/10/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>414 S 2ND ST</b>	Local Designation #	SHPO #