

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>110 S BLUFF ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 43 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>74</b> Lot: <b>2</b>	Map #: <b>22E31CA</b> Tax Lot #: <b>3300</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Vinyl double-hung</b>	
Exterior Surface Materials Primary: <b>Round-edge drop</b>		Secondary: <b>Plywood</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Gable ends and foundations clad with plywood, full window replacement.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This modest bungalow is part of a larger grouping of similar residential buildings. It sits under a front gable roof, with a gabled porch on the west side that runs nearly the full width of that façade. The gables feature open eaves and decorative knee brackets that penetrate the wide barge boards, typical of the style. The house is clad with double drop siding finished with cornerboards above the foundation level, with plywood cladding at the foundation and at the gable end on the porch. The windows are all vinyl sash replacements of the original windows with divided upper sashes and plain board surrounds. The porch gable is supported by a pair of square columns at the corners, and is surrounded by a new wood balustrade.			
Statement of Significance:			
Researcher/Organization: <b>Alex McMurry / HPNW</b>			Date Recorded: <b>3/25/2002</b>
<b>Survey Form Page 1</b>	Address: <b>110 S BLUFF ST</b>	Local Designation #	SHPO #