

### OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>111 S BLUFF ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 44 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>NA</b> Lot: <b>NA</b> Map #: <b>22E31CA</b> Tax Lot #: <b>3500</b>
Date of Construction: <b>c. 1945</b>	Historic Name:	Historic Use or Function: <b>Other - unknown</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Social - club</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Quonset</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Barrel Vault / Metal standing seam</b>		Window Type/Material: <b>2/2 double-hung</b>	
Exterior Surface Materials Primary: <b>Drop</b>		Secondary: <b>Plywood</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Entry added, west side.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Fair</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This building is a quonset hut serving as the American Legion Post 5 and the V.F.W. #1324. The building sits at the southeast corner of a large parking lot, with a rectangular bay added to the west side that houses the entry to the building. The main building is oriented north-south, and the arched roof is mirrored in the arched parapet on the entry wing. The entry is clad with plywood, while the north and south ends of the building are clad with drop siding. Two shed dormers on the west side house banks of five 2/2 double-hung wood sash windows with horizontally oriented panes and narrow trim molding. A small shed roof is cantilevered out from the north end of the building over an emergency exit.			
Statement of Significance:			

Researcher/Organization: <b>Alex McMurry / HPNW</b>		Date Recorded: <b>7/26/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>111 S BLUFF ST</b>	Local Designation #	SHPO #