

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 114 S CENTER ST				City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 07 N		Longitude: 122 36 39 W	
Township: 02S	Range: 02E	Section: 31	Block: 84	Lot: 7x	Map #: 22E31CA Tax Lot #: 2000
Date of Construction: c. 1911		Historic Name: Bradley, W.W., Rental		Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA		*Current Name or Use: Domestic - single dwelling		Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow			Plan Type/Shape: Rectangle		Number of Stories: 1.5
Foundation Material: Concrete block			Structural Framing: Unknown		Moved? No
Roof Type/Material: Gable / Composition shingle			Window Type/Material: 1/1 wood double-hung; large picture		
Exterior Surface Materials Primary: Round-edge drop			Secondary:		Decorative:
Exterior Alterations or Additions/Approximate Date: Dormer may be an early addition; concrete block foundation					
Number and Type of Associated Resources: Period garage (1)					
Integrity: Good		Condition: Good		Local Ranking: Designated Historic Site	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
Description of Physical and Landscape Features:					
This 1-1/2 story bungalow is rectangular in plan with a broken-pitch gable roof. The eave is supported by simple brackets and a large dormer punctuates the front elevation. The front porch is full-width, with a solid shingled rail and tapered truncated posts. On the south side there is a square bay. Wood shingles clad the gables as marked by a string course, and there is a hooded and bracketed attic bay on the south side. Siding is round-edge drop and the windows are 1/1 wood double-hung surround by a square trim. At the front, there are two large picture windows. Off the south corner of the house is a period garage clad in the same materials as the house.					
Statement of Significance:					
This house was a rental belonging to W.W. Bradley. Bradley ran a second-hand goods shop on Main Street and lived next door at 112 S. Center Street.					

Researcher/Organization: Bernadette Niederer / HPNW			Date Recorded: 4/6/2002		
Survey Form Page 1	Address: 114 S CENTER ST		Local Designation #		SHPO #