

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 409 S CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 00 N	Longitude: 122 36 48 W
Township: 02S	Range: 02E	Section: 31 Block: 78	Lot: 15, 16 Map #: 22E31CA Tax Lot #: 7900
Date of Construction: c. 1950	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Aluminum sliders	
Exterior Surface Materials Primary: Vertical groove plywo		Secondary: Wood shingle	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed addition to north façade; incompatible door			
Number and Type of Associated Resources: Enclosed carport to north (1)			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story minimal tract house has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles and is pierced by a chimneys. The house is covered with vertical groove plywood with lap siding on the gable ends. Windows are primarily sliding windows flanked by decorative shutters. The pent roof entry porch protects the recessed main entrance door and has wrought iron railings and posts. An enclosed carport is on the north side of the house.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 5/10/2002	
Survey Form Page 1	Address: 409 S CENTER ST	Local Designation #	SHPO #