

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 111 S HIGH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 10 N	Longitude: 122 36 42 W
Township: 02S	Range: 02E	Section: 31 Block: 74 Lot: 2	Map #: 22E31CA Tax Lot #: 3300
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing:	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 9/1 vinyl double-hung	
Exterior Surface Materials Primary: Round-edge drop Secondary: Vertical groove plywo Decorative:			
Exterior Alterations or Additions/Approximate Date: Porch incompatible with vertical groove plywood; vinyl grid windows; 1990s front door; vertical plywood near vestibule addition			
Number and Type of Associated Resources: None			
Integrity: Fair Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This one story bungalow has a square plan and sits on a poured concrete foundation. The gable roof is covered with composition shingles and has decorative eave brackets. The walls are clad in round edge drop siding. Windows are primarily 9/1 double-hung, vinyl grid windows. The gabled-roof front porch has vertical wood knee wall and vertical wood siding in the gable end. A vertical plywood vestibule has been added to the rear.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 111 S HIGH ST	Local Designation #	SHPO #