

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 110 S JOHN ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 04 N	Longitude: 122 36 31 W
Township: 02S	Range: 02E	Section: 31	Block: NA Lot: NA Map #: 22E31DB Tax Lot #: 7500
Date of Construction: c. 1948	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 8-pane fixed	
Exterior Surface Materials Primary: Wood shingle		Secondary: Vertical T&G	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed roof addition to rear			
Number and Type of Associated Resources: Period garage to east (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story minimal tract house is rectangular in plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles. The house is covered with wood shingles and vertical tongue and groove siding in the gable ends. Windows are primarily multi-pane fixed flanked by faux shutters. Windows on the south façade are vinyl. The entry door is protected by a small gable roof. There is a shed roof addition to the rear. A detached garage is behind the house.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 110 S JOHN ADAMS ST	Local Designation #	SHPO #